



- Federal Navigation Channel
- Shoaling Area
- Placement Area
- - - Anchorage Area
- ▨ Wreck Area
- ▲ Submerged Wreck
- △ Angle Points
- Beacon, General
- Obstruction Point
- ◆ Navigation Buoy
- ◆ Navigation Buoy
- Shoalest Sounding*
- Contour Lines
- Every 10' Contours From -10' -to -60'

NOTES:
DRAWING NOT TO BE USED FOR NAVIGATION, ONLY CHANNEL CONDITION AT DATE OF SURVEY.
THE LOCATION OF ALL NAVIGATION AIDS ARE BASED ON INFORMATION PROVIDED BY THE U.S. COAST GUARD. BUOY LOCATIONS REPRESENT THE POSITION OF THE SINKER ONLY.
SURVEYED BY THE CORPS OF ENGINEERS.
SOUNDINGS ARE TAKEN BY FATHOMETER AND ARE SHOWN TO THE NEAREST FOOT AND TENTHS OF A FOOT.
SOUNDINGS ARE BASED ON THE DATUM OF MEAN LOWER LOW WATER AT THE LOCALITY.
PLANE GRID, BEARING AND COORDINATES ARE BASED ON LAMBERT PROJECTION, ZONE III NAD 83, CALIFORNIA, AS DESCRIBED IN SPECIAL PUBLICATION NO. 236, PUBLISHED BY NATIONAL OCEAN SURVEY.
PROJECT DEPTH IS 50 FEET AT M.L.L.W.
SOUNDINGS ARE BASE TIDE GAUGE LOCATED AT MARE ISLAND COAST GUARD DOCK VERTICAL CONTROL U-466
1950 USC&GS DISK ELEV. 13.99 FT MLLW TIDAL 5218L USC&GS ELEV. 411.04 FT MLLW
HORIZONTAL CONTROL COAST GUARD D-BEACON

W W W
US Army Corps
of Engineers
San Francisco District
1455 Market Street
San Francisco, CA 94103

Distribution Liability: The data represents the results of data collection/processing for a specific US Army Corps of Engineers activity and includes the general existing conditions. It is intended for use by the United States Government and its contractors for engineering purposes. It is not to be distributed outside the United States without the express written consent of the US Army Corps of Engineers. It is not to be used for any other purpose than its intended purpose.

PREPARED UNDER THE DIRECTION OF	Surveyed By:	Chart Date:
JOHN C. MORROW LT. COLONEL, E. DISTRICT ENGINEER	PDT	Oct 01, 2014
Submitted:	Designed by:	
Hydro Survey Team Leader		
Recommended:	Drawn by:	
Chief Hydro Survey Section		
Approved:	Checked by:	
Chief Construction Branch		

CALIFORNIA
CARQUINEZ STRAIT - SF 9
CONDITION SURVEY
30 SEPTEMBER 2014

Sheet
Reference
Number
1 of 1