Suisun Bay North Channel Light 2

PRELIMINARY ISSUE
NOT FOR SURVEY OR ADVANCE NAVIGATION USE

SF 16 DISPOSAL NAD 83
CHANNEL ANGLE POINTS

∠ PT	X	Y
31	6531326.1400	1779351.3500
32	6530944.9400	1730503.4500
33	6530263.0400	1731433.2500
34	6537502.4400	1732043.3500
35	6542439.3400	1736229.3500
36	6542719.4400	1734309.9500
37	6537742.3400	1731693.5500
38	6536439.3400	1731614.1500
39	6533237.1400	1730944.1500
310	6532941.9400	1779415.3500

SF 16 DISPOSAL NAD 83
CENTERLINE ANGLE POINTS

∠ PT	X	Y
21	6531944.0400	1779361.3500
22	6533141.0400	1730270.2500
23	6536351.2400	1731243.7500
24	6537822.4400	1731323.8500
25	6542574.3400	1735319.7500

BULLSHEAD CHANNEL

Suisun Bay Channel Lighted Buoy 6

MATCHLINE - SHEET 1

MATCHLINE - SHEET 3

GRAPHICS SCALE 1" = 200'

200' 0 100' 200' 400' 800'

FLOOD

EBB

US Army Corps of Engineers
San Francisco District
1455 Market Street
San Francisco, CA 94105

No.	Description	Date	Appr.

DESIGNED BY: PDT
DRAWN BY: PDT
CHECKED BY: PDT
DRAWING NO. 4 2
SHEET NO. 2 OF 16
DATE: 6/21/2010

SUBMITTED: PDT
Survey Section Team Leader

APPROVAL RECOMMENDED:
STEPHEN P. KILMON, P.S.M.
Chief, Geomatics Section

APPROVED:
Chief, Construction Branch

PREPARED UNDER THE DIRECTION OF
LAURENCE M. FARRELL
LT. COLONEL, C.E., DISTRICT ENGINEER

CONTRA COSTA COUNTY CALIFORNIA

SUISUN BAY CHANNEL
CONDITION SURVEY
6-12 JUNE 2010

Sheet reference number
G2