




NOTES:

1. THE LOCATION OF THE NAVIGATION AIDS WERE PLOTTED FROM DATA FURNISHED BY THE 11TH COAST GUARD.
2. BUOY LOCATIONS REPRESENT THE POSITION OF THE SINKER ONLY.
3. DRAWINGS NOT TO BE USED AS NAVIGATION CHART AND REPRESENT ONLY THE CHANNEL CONDITION AT THE TIME OF THE SOUNDINGS.
4. DATE OF SOUNDINGS: APRIL 18, 2014
5. 35' DEPTH LINE SHOWN IN CHANNEL.
6. AERIAL PHOTOGRAPHY TAKEN IN 2008



Rev	Date	Approved	Rev #
1	15-MAY-2014	BRYAN HOLM	1
2	15-MAY-2014	BRYAN HOLM	2
3	15-MAY-2014	BRYAN HOLM	3
4	15-MAY-2014	BRYAN HOLM	4
5	15-MAY-2014	BRYAN HOLM	5
6	15-MAY-2014	BRYAN HOLM	6
7	15-MAY-2014	BRYAN HOLM	7
8	15-MAY-2014	BRYAN HOLM	8
9	15-MAY-2014	BRYAN HOLM	9
10	15-MAY-2014	BRYAN HOLM	10

DESIGNED BY:	BRYAN HOLM	DATE-APPROVED:	15-MAY-2014
DRAWN BY:	B. HOLM	DESIGN FILE NO.:	52-06-0417
REVIEWED BY:	RICHARD A. TORBIC	DRAWING CODE:	CONDITION SOUNDINGS
SUBMITTED BY:	RICHARD A. TORBIC	FILE NAME:	1325 J STREET
DATE:	15-MAY-2014	PLOT DATE:	15-MAY-2014
SCALE:	1" = 200'	PLOT SCALE:	1" = 200'

STOCKTON DWSC	CALIFORNIA
SF BAY TO STOCKTON, CALIFORNIA	
JOHN F. BALDWIN AND	
STOCKTON SHIP CHANNELS	
IDIQ MAINTENANCE DREDGING	
CONDITION SOUNDINGS	
CHANNEL MILE 40.2 TO MILE 41.1	

Sheet
reference
number:
39
Sheet 39 of 39